Incident on January 10, 2016

Smoke Alarm in Vault

First Responders attended Winnipeg Cyclotron Facility (WCF) approximately 1530h SUN 10 JAN 2016 in response to a smoke alarm in Cyclotron vault.

A strong smell was noted, smoke or fire were not observed.

First Responders did not enter any CNSC-classified rooms.

WCF Radiation Safety Officer (RSO) attended WCF with hospital security, and inspected entire Cyclotron facility; no concerns identified.

CNSC Duty Officer was informed verbally by telephone SUN evening.

CNSC Class II Nuclear Facilities Project Officer was informed by voice-mail message and e-mail MON 11 JAN.

WCF Cyclotron Specialist thoroughly checked the Cyclotron at 0630h MON 11 JAN; no issues were identified.

No effects to environment or health.

20160111 Smoke Alarm in Vault PDF.pdf